

















**Safety Pilot or Ignition System Originally Supplied, Identified by Serial No. Code (cont'd)—See Serial No. Decoding on pages 3–4.**

Code	Description	PN(s)	Replaced by	Code	Description	PN	Replacement
88	Varidigm VB4-H700 Combustion Board (RDCB/RDDB H700)	223556-N/A 	Contact your local Representative or the factory for replacement information.	94	UTC #1003-638-A Recycling Ignition Controller	257009 	
89	Varidigm VB4-H800 Combustion Board (RDCB/RDDB H800)	222678-N/A 	Contact your local Representative or the factory for replacement information.	95	UTC #1003-514 Ignition Controller with Lockout	257010 	
90	UTC #1097-211 Direct Spark Ignition and Varidigm VB4-H500 Combustion Board (RDCB/RDDB H10C)	195573  223554-N/A 	PN 223554 is no longer available. Contact your local Representative or the factory for replacement information.	96	Varidigm VB1200-5-RZNR-C	257246 	<b>NOTE:</b> If CODE 96 board is replaced, the ID plug must either be replaced also or removed and installed on the new board. See page 10 for a list of ID plugs.
91	UTC #1097-211 Direct Spark Ignition and Varidigm VB4-H600 Combustion Board (RDCB/RDDB H12C)	195573  223555-N/A 	PN 223555 is no longer available. Contact your local Representative or the factory for replacement information.	97	Varidigm VB1200-5-RZNR-AB	258319 	<b>NOTE:</b> If CODE 97 board is replaced, the ID plug must either be replaced also or removed and installed on the new board. See page 10 for a list of ID plugs.
92	UTC #1097-211 Direct Spark Ignition and Varidigm VB4-H700 Combustion Board (RDCB/RDDB H14C)	195573  223556-N/A 	PN 223556 is no longer available. Contact your local Representative or the factory for replacement information.	98	Varidigm VB1200-2-RZNR-PVA	260252 	<b>NOTE:</b> If CODE 98 board is replaced, the ID plug must either be replaced also or removed and installed on the new board. See page 10 for a list of ID plugs.
93	UTC #1097-211 Direct Spark Ignition and Varidigm VB4 Combustion Board (RDCB/RDDB H16C)	195573  222678-N/A 	PN 222678 is no longer available. Contact your local Representative or the factory for replacement information.	99	Varidigm VB1200-5-RZNR-SHH	260917 	<b>NOTE:</b> If CODE 99 board is replaced, the ID plug must either be replaced also or removed and installed on the new board. See page 10 for a list of ID plugs.
A1	Direct Spark Ignition, UTC #1097-218, 7 Sec TFI					269867 