



**Code 758 - Replacement Door Latch Kit, P/N 112974**

Assembly sequence for installing replacement door latch.

Code	Description	Qty	RBA	RBHA	RBL	
798	Motor Mount Support Assembly	RBL - see illustrations on pg 52	2	--	--	106698 (< 15HP mtr)
			1	--	--	149008 (15 & 20 HP)
799	Motor Adjustment Bracket Assembly	RBA - see btm of page;	1	44411	--	106274 (< 15HP mtr)
		RBL-see pg 52	1	(Less than 1HP)	--	149009 (15 & 20 HP)
799A	Motor Adjustment Angle	RBL - see illustrations on pg 55	1	--	--	105633 (< 15HP mtr)
			1	--	--	149010 (15 & 20 HP)
800	Hardware Bag (for motors less than 1 HP)	1		64940	--	
801	Motor Mounting Strap 12" (for < 1 HP)	1	44410	--	--	
802	Motor Mounting Plate	RB(H)A-see below; RBL - see pg 52	1	12579, 1-3 HP mtr	12578	106295 (Assembly)
				12578, 5HP motor		
803	Motor Mounting Plate Left Support	1		12576	--	
804	Motor Mounting Plate Right Support	1		12577	--	
805	Blower Housing and Wheel		1360, A12-12AC	112606, A12-12AC unpainted	(2) 14469, Lau 15 x 11	
806	Blower Shaft	1	11303, 1" x 22" lg	112608, 1" x 45" lg	13589, 1-3/16 x 48" lg	
807	Bearings	2	10437	15298	14474 (< 10 HP)	
808	Bearing Bracket	2	--	--	24233 (< 10 HP)	
809	Heavy Duty Blower (15-20HP Mtrs) Rt	1	--	--	106937, 15 x 11	
810	Heavy Duty Blower (15-20HP Mtrs) Lft	1	--	--	106938, 15 x 11	
811	Heavy Duty Blower Shaft 15-20HP Mtr	1	--	--	106941, 1-7/16" x 53" lg	
812	Blower Shaft Key for Heavy Duty Blwr	4	--	--	134638	
813	Pillowblock Bearings, Dodge #P2BS2107R, 1-7/16"	2	--	--	170108 (replaces 106942)	
814	Class II Blower Support - Right Side	1	--	--	149520	
815	Class II Blower Support - Left Side	1	--	--	149521	
816	Filter Rack Middle	1" & 2" Filters	1	104059	--	
817	Filter Rack Btm	1" & 2" Filters	1	104073	--	
818	Filter Rack Top	1" Filters	1	--	114721	
819	Filter Rack Btm	1" Filters	1	--	114713	
820	Filter Rack Rear	1" Filters	2	--	114709	
821	Filter Rack Front	1" Filters	2	--	114697	
822	Filter Rack Rear	2" Filters	1	--	114725	
823	Filter Rack Btm	2" Filters	1	--	114717	
824	Filter Rack Rear	2" Filters	2	--	114705	
825	Filter Rack Front	2" Filters	2	--	114693	

**Code 799 for RBA - Motor Adjustment Bracket used on RBA with less than 1HP Motor**

**Code 800 for RBA - Replacement Hardware Bag for Code 799**

**Code 801 for RBA with motors less than 1HP**

**Codes 802-804 for RBA and RBHA with 1-5HP Motor**

(6) Bolts, P/N 16247

(2) Rod Bolts, P/N 12489

(2) Bolts, P/N 16248; Nuts, P/N 6445; Washer, P/N 1087